


56	12,96	6 = 13800
51	12,96	4 + 1 = 11600
45	12,96	4 = 10200


● = 2550    B = 1400




3-11,6	12	14	16	18	20	22,3	25	28	31	34	35	38	41	44	47	50	53	56
8	7,73	6,54	5,65	4,95	4,4	4,0	3,51	3,08	2,74	2,45	2,37	2,16	1,95	1,79	1,64	1,51	1,40	1,30




3-12,0	14	16	18	20	22	23,0	25	28	31	34	35	38	41	44	47	50	51
8	6,77	5,85	5,13	4,56	4,09	4,0	3,64	3,2	2,84	2,55	2,46	2,23	2,03	1,86	1,71	1,58	1,54



3-12,2	14	16	18	20	22	23,3	25	28	31	34	35	38	40	42	44	46
8	6,86	5,93	5,21	4,63	4,15	4,0	3,69	3,25	2,89	2,59	2,50	2,27	2,13	2,0	1,89	1,79



3-12,4	14	16	18	20	22	23,7	25	28	31	34	35	38	40	41
8	6,99	6,04	5,30	4,71	4,23	4,0	3,77	3,31	2,94	2,64	2,55	2,31	2,17	2,11



	/						
	/	8,5	40	80	4,2	20	40
		4,0	4,0	2,0	8,0	8,0	4,0
		24					
	/	40/20					
		3,3/2,2					
	/	0 ~ 0,62					
		3,7 x 2					
		34,7					